

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: JASPER COUNTY

Community No: 180439

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

**1. LOMCs Incorporated**

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

**2. LOMCs Not Incorporated**

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	01-05-1511A	04/11/2001	PORTION OF SECTION 13-27-7; 6474 WEST 1600 SOUTH	1804390007B	18073C0393C
LOMA	01-05-2847A	07/25/2001	PORTION OF SECTION 11, T 28 N, R 7 W; 8834 WEST EGYPT ROAD	1804390005B	18073C0290C
LOMA	04-05-1249A	02/13/2004	PART OF SEC. 31, T 30 N, R 6 W, 2ND PM; 746 S. US HIGHWAY 231	1804390005B	18073C0200C
LOMA	05-05-2832A	05/19/2005	13318 SOUTH 680 WEST -- PORTION OF SECTION 2, T27N, R7W	1804390007B	18073C0395C
LOMA	06-05-B854A	04/25/2006	6245 WEST 800 SOUTH -- PORTION OF SECTION 12, T28N, R7W (IN)	1804390005B	18073C0293C
LOMA	06-05-BJ55A	06/15/2006	9428 EGYPT ROAD -- PORTION OF SECTION 14, T28N, R7W (IN)	1804390005B	18073C0290C
LOMA	06-05-BQ28A	07/14/2006	6436 WEST 1600 SOUTH -- PORTION OF SECTION 13, T27N, R7W (IN)	1804390007B	18073C0393C
LOMA	08-05-1415A	02/19/2008	10550 WEST 1300 NORTH -- PORTION OF SECTION 20, T32N, R7W	1804390001B	18073C0085C

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: JASPER COUNTY

Community No: 180439

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	11-05-1629A	04/19/2011	PARCEL 1 -- 1121 15TH AVENUE NORTHWEST	1804390001B	18073C0079C

**3. LOMCs Superseded**

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

**4. LOMCs To Be Redetermined**

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		